

Inspection Photos

12/07/2017

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312291

Inspection Doc. Number: 682502927

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 1: Photo taken from the southeast end of the location, facing southeast. Photo shows areas of erosion degradation. Erosion has not been repaired or stabilized and no BMPs have been installed or maintained per corrective actions.



Photo 2: Photo taken from the southeast end of the location (northeast of pit), facing southeast. Photo shows areas of erosion degradation on the adjacent lands due to runoff and salt kill. Photo shows no remediation activities appear to have been conducted, and no stabilization and stormwater BMPs have been installed or maintained per the corrective actions.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 3: Photo taken from the southeast corner of the pit, facing north. See comments under photo 2.



Photo 4: Photo taken from the southeast corner of the pit, facing west. See comments under photo 2.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312291



Photo 5: Photo taken from the southwest corner of the pit, facing northeast. See comments under photo 2.



Photo 6: Photo taken from the west end of the location, facing west. Photo shows areas of erosion degradation. Erosion has not been repaired or stabilized and no BMPs have been installed or maintained per corrective actions.