

Location Name: McIntyre 34-16 flowline release Spill ID 453260 Inspection Date: 12/8/2017



Photo 1 – Viewing southeast corner of final excavation extents. DCP line in foreground.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: McIntyre 34-16 flowline release Spill ID 453260 Inspection Date: 12/8/2017



Photo 2 – Viewing final excavation extent, looking northwest. DCP line runs north-south in excavation. Base of excavation remains to be excavated.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources