

## Inspection Photos

Location Name: **BHD #1**

API: 05-103-05106



**Location**



**Blow down pit with animal burrow**

## Inspection Photos

Location Name: **BHD #1**

API: 05-103-05106



**Blow down pit with animal burrow**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources