

Inspection Photos
Location Name: DGU Fed 1289 Sec 18 Pad
Location ID: 427218



Photo 1. Risers marked and LOTO.



Photo 2. Location graded and vegetation removed.

Inspection Photos
Location Name: DGU Fed 1289 Sec 18 Pad
Location ID: 427218



Photo 3. Stored equipment has been removed.