

Photo#1:

Overview of Location from Entry to North. Large areas remain Unreclaimed.



December 7, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra PA Crystal Creek API#045-06476

Photo#2:

Noxious Weeds (Thistle) are still established on Location



December 7, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra PA Crystal Creek API#045-06476



Photo#3:

Equipment remains on Location .

Photo#4:



December 7, 2017