

Grand Mesa Operating CO, Easy Come 2
073-06697

Inspection #688300751

12/5/2017

Routine Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


A black metal structure, possibly a wellhead or part of a drilling rig, stands in a desert landscape. A black sign with white text is attached to the structure. The sign reads: "GRAND MESA OPERATING COMPANY", "EASY COME #2", and "NW NE SECT 2-6S-54W". The background shows a vast, flat, arid landscape under a clear blue sky. In the distance, a small structure and a vehicle are visible on a ridge. The foreground is filled with dry, cracked earth and shadows cast by the structure.

GRAND MESA OPERATING COMPANY
EASY COME #2
NW NE SECT 2-6S-54W

12.05.2017



12.05.2017



3632171

GRAND MESA OPERATING COMPANY
316-265-3000
EASY COME LEASE
NW NE SECT 2 -6S-54W; RD 0 AND RD 35
LINCOLN COUNTY, CO

12.05.2017



12.05.2017



12.05.2017