

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/07/2017

Submitted Date:

12/08/2017

Document Number:

688300772

FIELD INSPECTION FORM

Loc ID 452770 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 35080
Name of Operator: GRAND MESA OPERATING CO
Address: 1700 N. WATERFRONT PKWY BL 600
City: WICHITA State: KS Zip: 67206

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452771	WELL	XX	10/28/2017		073-06730	SEQUOIA 1-36	DG

General Comment:

Surface Cementing

Location

Overall Good:

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 452771 Type: WELL API Number: 073-06730 Status: XX Insp. Status: DG**Well Drilling**Rig: Rig Name: WW Drilling Rig 20 Pusher/Rig Manager: Paco
Permit Posted: Yes Access Sign: _____**Well Control Equipment:**Pipe Ram: NO Blind Ram: NO Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES**Drill Fluids****Management:**Lined Pit: YES Unlined Pit: NO Closed Loop: NO Semi-Closed Loop: _____
Multi-Well: NO Disposal Location: On locationComment: Surface TD 437', pipe to 417', 8 5/8", 24 wt

Corrective Action: _____

Date: _____

Cement**Cement Contractor**Contractor Name: QES Contractor Phone: _____**Surface Casing**Cement Volume (sx): 375 Circulate to Surface: YES
Cement Fall Back: _____ Top Job, 1" Volume: _____**Intermediate Casing**

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: Class A, 15.1 ppg, finished at 11:00 pm on 12/7/2017

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300773	Grand Mesa Sequoia 1-36 CEM	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4323064