

Inspection Photos
Location Name: Pherson #2-2
API: 05-123-12473



Photo 1: Location looking SW



Photo 2: Weeds growing inside tank berm



Inspection Photos
Location Name: Pherson #2-2
API: 05-123-12473



Photo 3: Trash on location



Photo 4: Deactivated riser SE of separator

Inspection Photos
Location Name: Pherson #2-2
API: 05-123-12473



Photo 5: Wellhead looking S. Well currently TA