



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*), mixed wheatgrasses, and blue grama (*Bouteloua gracilis*).





Photo 4. View of stormwater controls on the access road that appear to be functioning.