

Inspection Photos
Location Name: Loustalet #B15-10
API: 05-123-15011



Photo 1: Location, looking NE



Photo 2: Wellheads, looking N. Debris around wellheads.

Inspection Photos
Location Name: Loustalet #B15-10
API: 05-123-15011



Photo 3: Vaults not anchored in floodplain.



Photo 4: Debris along lease road.