



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Dec 12, 2017 4:40:19 PM MST
Server Receive Date:	Dec 12, 2017 4:40:34 PM MST
Reference Number:	20171212-1870532092
Location:	36 Road 3522, Flora Vista, NM 87415, United States Dec 12, 2017 4:37:22 PM MST [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Dec 12, 2017
Well Name	BEUTEN GAS UNIT A 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs

Picture North to South



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

