

Inspection Photos

Location Name: Hamilton 25-10B

API #: 05-123-15392

Location ID: 327982



Wellhead looking north



Battery looking south

Inspection Photos

Location Name: Hamilton 25-10B

API #: 05-123-15392

Location ID: 327982



Inadequate berm wall at load line bucket, needs repaired



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources