

Inspection Photos

12/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 329551

Inspection Doc. Number: 682502958

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329551



Photo 1: Photo taken from the south end of the well location, facing north. Photo shows vegetation over the reclamation area has not achieved a uniform cover and does not appear to be progressing to 80% cover to that of the reference. Photo also shows no reclamation activities appear to have been conducted per the corrective action.



Photo 2: Photo taken from the north end of the well location, facing east. Photo shows vegetation over the reclamation area has not achieved a uniform cover and does not appear to be progressing to 80% cover to that of the reference. Photo also shows no reclamation activities appear to have been conducted per the corrective action.



Photo 3: Photo of the disturbance area of the well location. Photo shows vegetation is predominantly undesirable weedy plant species. Photo also shows no reclamation activities appear to have been conducted per the corrective action.



Photo 4: Photo taken from the adjacent reference area. Reference area is a irrigated hay meadow composed predominantly of perennial grass.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329551



Photo 5: Photo taken from the north end of the former tank battery location, facing south. Photo shows majority of the battery facility appears to have been seeded and crimped with straw for stabilization.



Photo 6: Photo taken from the former tank battery location, facing south. Previous inspections required operator to remove equipment (meter shed) in accordance to 1004.a. Photo shows equipment has not been removed.