

Inspection Photos

12/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 327399

Inspection Doc. Number: 682502960

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327399



Photo 1: Photo taken from the south end of the well location, facing north. Photo also shows no reclamation activities appear to have been conducted per the corrective action. Photo shows vegetation is predominantly undesirable weedy plant species such as kochia and/or Russian thistle.



Photo 2: Photo taken from the well location, facing east. Photo shows vegetation over the well location. Vegetation is predominantly undesirable weedy plant species such as kochia and/or Russian thistle. Unable to find evidence that reclamation activities have been conducted at the well location. This corrective action remains applicable.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327399



Photo 3: Photo taken from the adjacent reference area of the well location. Vegetation seen here appears to be predominantly desirable perennial vegetation such as sand dropseed.



Photo 4: Photo taken from the east end of the former battery facility, facing southwest. Photo shows majority of the battery facility appears to have been seeded and crimped with straw for stabilization.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327399



Photo 5: Photo taken from the east end of the former tank battery location, facing northwest. Photo shows majority of the battery facility appears to have been seeded and crimped with straw for stabilization. Photo also shows meter shed equipment has not been removed per the corrective action.



Photo 6: Photo taken from the east end of the former tank battery location, facing north. Photo shows majority of the battery facility appears to have been seeded and crimped with straw for stabilization.