

Inspection Photos

12/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 332748

Inspection Doc. Number: 682502968

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the battery location, facing west. Previous inspections required operator to remove four (4) pipe risers on the battery location in accordance to reclamation rule 1004.a. Photo shows two risers have been removed, however two risers remain on the location.