

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/08/2017

Submitted Date:

12/08/2017

Document Number:

679700686**FIELD INSPECTION FORM**
 Loc ID 329266 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	
Greg Becker		gregory.becker@greeleygov.c om	Greeley Fire Department

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249282	WELL	SI	04/01/2017	OW	123-17084	MCINTYRE 34-16	EI
453260	SPILL OR RELEASE	AC			-	McIntyre 34-16 flowline	EI

General Comment:

Inspected Facilities									
Facility ID:	<u>249282</u>	Type:	<u>WELL</u>	API Number:	<u>123-17084</u>	Status:	<u>SI</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>453260</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	No impacted soil stored onsite. Final excavation extent is being completed with hydrovac, and all material hauled for disposal.			
Corrective Action				Date:

Spill/Remediation:

Comment:	COGCC inspection of final excavation exten at release on McIntyre 34-16 flowline. Excavation was nearly complete with final field readings indicating horizontal extent of impacts had been delineated and impacts removed. Operator indicates that monitoring well installation is planned for 12/14/2017.		
Corrective Action:	Operator shall submit Form 27 with results of excavation, monitoring well installation and planned future monitoring. Form 27 due as stated on previous inspection.		
			Date: 02/03/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401480880	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321548
679700687	Excavation photos 12-8-2017	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321537