

Inspection Photos
Location Name: Allison Unit #147
API: 05-067-08350



ASTs still have Conoco Phillips labels on them.



Allison Unit #147 pumping unit and well head.

Inspection Photos
Location Name: Allison Unit #147
API: 05-067-08350



Well head and surrounding area stained with white residue.



Stained concrete pad and surrounding area near muffler exhaust.