

Inspection Photos
Location Name: IGE #139
API: 05-067-09534



Frac sand dumped on location.



Horizontal tank at end of blooie line.

Inspection Photos
Location Name: IGE #139
API: 05-067-09534



Hurricane Rig #10 on location.



New valve on tank load out line.