

Inspection Photos
Location Name: Schneider 22-21
API #: 05-123-16090
Location ID: 328521



Wellhead looking east



Unused tubing south of wellhead needs to be removed