

Inspection Photos
Location Name: Kowitz 27-5
API #: 05-123-13474
Location ID: 323750



Wellhead looking south. Well is TA



Battery looking north

Inspection Photos
Location Name: Kowitz 27-5
API #: 05-123-13474
Location ID: 323750



Stained soil inside and outside of separator doghouse



Paint is chipping on crude oil tank and has visible rust