

Inspection Photos
Location Name: HSR Loeffler 8-27
API #: 05-123-16749
Location ID: 329014



Wellhead looking north



Battery looking west

Inspection Photos

Location Name: HSR Loeffler 8-27

API #: 05-123-16749

Location ID: 329014



Crude oil tank does not have NFPA placard



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources