

Inspection Photos
Location Name: Strong 4-22
API #: 05-123-11858
Location ID: 332567



Wellhead sign looking west



Wellhead looking south, fiberglass enclosure around wellhead

Inspection Photos
Location Name: Strong 4-22
API #: 05-123-11858
Location ID: 332567



Battery looking north



Stained soil under load line valve on crude oil tank

Inspection Photos
Location Name: Strong 4-22
API #: 05-123-11858
Location ID: 332567



Leaking fittings on separator