

Inspection Photos

12/18/2017

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 319767

Inspection Doc. Number: 682502972
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 319767



Photo 1: Photo taken from the south end of the former battery facility, facing east. Previous inspections required operator to perform weed management. Photo shows weeds have not been managed or removed per the corrective actions.



Photo 2: Photo taken from the south end of the former battery facility, facing northwest. Previous inspections required operator to perform weed management. Photo shows weeds have not been managed or removed per the corrective actions.



Photo 3: Photo taken from within the former battery facility. Previous inspections documented that Canada thistle (*Cirsium arvense*) was present and required its removal. Canada thistle is a listed noxious weed is required to be managed under COGCC, Colorado State and Adams County requirements. Photo shows stalks of Canada thistle that were previously documented. Photo shows operator has not removed or managed weeds on the location.