

Inspection Photos

12/18/2017

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 311680

Inspection Doc. Number: 682502982
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 1: Photo taken from the west end of the location, facing southeast. Photo shows western slope of the well pad location has been recontoured/regraded and stabilized per the CA.



Photo 2: Photo taken from the west end of the location, facing east. Photo shows additional reclamation activities appear to have been conducted per the CA

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 3: Photo taken from the west end of the location, facing northeast. Photo shows additional reclamation activities appear to have been conducted per the CA



Photo 4: Photo taken from the west end of the location, facing south. Photo shows areas where reclamation was required on the access road appear to have been conducted.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 5: Photo taken southwest corner of the well location, facing east. Photo shows well pad appears to have been recontoured/regraded, seeded and stabilized w/ matting.



Photo 6: Photo taken southwest corner of the well location, facing north. Photo shows well pad appears to have been recontoured/regraded, seeded and stabilized w/ matting.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311680



Photo 7: Photo taken from the southeast end of the location. Photo shows areas where erosion degradation was evident appear to have been repaired and stabilized.



Photo 8: Photo taken from the southeast end of the location. Photo shows areas where erosion degradation was evident appear to have been repaired and stabilized.