

Inspection Photos

12/18/2017

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 311698

Inspection Doc. Number: 682502984
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311698



Photo 1: Photo taken from the west of the location, facing east. Previous inspections required operator stabilize the location and drainage to prevent further incision and erosion, and to perform reclamation. Photo shows no reclamation activities appear to have been conducted.



Photo 2: Photo taken from the west of the location. Previous inspections required operator stabilize the location and drainage to prevent further incision and erosion, and to perform reclamation. Photo shows no reclamation activities appear to have been conducted at access road(s).