



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 4. View of musk thistle (*Carduus nutans*) within the eastern project area.