



02353204

UN243

# COLORADO OIL & GAS CONSERVATION COMMISSION

## NORTHEAST REGION FIELD INSPECTION REPORT


☐ NOTICE OF UNSATISFACTORY INSPECTION

☒ NOTICE OF SATISFACTORY INSPECTION

337 Cambridge

Brush, CO 80723 970-842-4465

Date: 3-17-2000

Facility ID:

Operator:

NENW 9 9N 61W

Location:

NENW 9- 9N-61W

Lease Name:

Gillette 5

API Number: 05 - 123 - 05703

Inspector:

ED BINKLEY

Cell: 970-380-2683

INSP TYPE

CA

INSP STATUS

1A

PA

☒

N

PASS/FAIL

☒

F

VIOLATION

Y

N

NOV

Y

N

UIC VIOL TYPE

UA

MI

OP

PA

OT

TBG/PKR LK

☐

CSG LK

☐

ALL UIC VIOLATIONS REQUIRE NOAYS

Well ID Signs

Comments:

Fences Y N

Comments:

(Rule 210) Y N

(Rule 603.b.(7), 1002.a)

Production Pits

(Rule 902, 903, 904)

EARTHEN PITS ONLY

Produced Water Pits

Total #

Oil Accumulation?

☐

YES

☐

NO

Comments:

Skimming/Settling Pits

Total #

Covered #

Uncovered #

Comments:

Special Purpose Pits

Total #

Lined #

Unlined #

Comments:

SENSITIVE AREA

☐

YES

☐

NO

Tank Battery Equipment

(Rule 604)

BURIED OR PARTIALLY BURIED VESSELS : #STEEL

#FIBERGLASS

#CONCRETE

#OTHER

Fire Walls/Berms/Dikes

[Rule 604.a.(4)]

General Housekeeping

(Rule 603.g)

Spills (Oil/Water)

(Rule 906)

UIC Routine Inspection

FILL OUT FORM 21

WHEN WITNESSING MIT

Inj. Pressure

Psig

T-C Ann. Pressure

Psig

COMMENTS

Drilling Well/Workover

(Rule 317)

Surface Rehabilitation

(Rule 1003, 1004)

Miscellaneous

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well See