

Inspection Photos  
Location Name [HL 11-89-19 #1](#) 1



**Photo 1 Location photo**

Inspection Photos  
Location Name [HL 11-89-19 #1](#) 1



**Photo 2 No tank labels or Emergency Contact Information**



Inspection Photos  
Location Name [HL 11-89-19 #1](#) 1



**Ope Photo 3 Erosion on Cut Slope of location**

Inspection Photos  
Location Name [HL 11-89-19 #1](#) 1



**Photo 4 Migration of sediment onto pad surface.**



Inspection Photos  
Location Name [HL 11-89-19 #1](#) 1



**Photo 5 Saw dust piled and blowing past location berm.**

Inspection Photos  
Location Name [HL 11-89-19 #1](#) 1



**Photo 6 Solids tank with no containment**