



**GP-26 CO2 Well
Facility ID 432955 / API #05-083-06703**

Field Inspection Form (Doc #680602290) – FIRR (Doc #401493217)



Photo 1

Access Road Culvert Outlet Improvements – Looking North



Photo 2

Access Road & Well Pad Surface Re-contouring – Looking East



Photo 3

New Diversion Ditch on South side of Well Pad – Looking East



Photo 4

New Diversion Ditch on North side of Well Pad – Looking East



Photo 5

New Diversion Ditch on East side of Well Pad – Looking South



Photo 6

New Diversion Ditch w/Rock Check Dams on North side of Access Road – Looking East



Photo 7

New Diversion Ditch on Northeast side Well Pad – Looking Southeast



Photo 8
New Rock Apron North side of Access Road – Looking East



Photo 9
New Diversion Ditch w/Rock Check Dams on South side of Access Road – Looking East



Photo 10

New Berm prior to Seed & Straw Application on West side of Well Pad – Looking North



Photo 11

New Berm w/ Seed & Straw Application on West side of Well Pad – Looking North