

Inspection Photos
Well Name: Federal 11-90-35#1
Location ID: 324471



Photo 1. Unused tanks have been removed and location graded.



Photo 2. New NFPA labels have been ordered, but the capacity had not been added to tank at the time of inspection.