

Inspection Photos
Location Name: Surprise Unit 2-08H
API: 05-057-06526



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Rills transporting sediment onto location on east side of location.