

Inspection Photos
Location Name: Surprise Central Facility
Location ID: 436676



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. No capacity on tank labels.