

Inspection Photos

12/20/2017

Operator: DCP MIDSTREAM LP - 4680

Facility ID: 453454

Inspection Doc. Number: 682502995

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the western half of Noble's Stewart Tank Battery Facility, facing northwest. Photo shows two pipe riser that has been identified as belonging to DCP. Risers require removal in accordance to 1004.a