

Inspection Photos

12/20/2017

Operator: DCP MIDSTREAM LP - 4680

Facility ID: 453456

Inspection Doc. Number: 682503000

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the eastern half of Extraction's Brantner Tank Battery Facility, facing southeast. Photo shows an abandoned pipe riser that has been identified as belonging to DCP. Riser requires removal in accordance to 1004.a.