

Interim Reclamation Inspection

December 15, 2017

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

API: 05-123-22704

Weld County, CO

NWSW Section 27 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: 70 RANCH #13-27
API: 05-123-22704



Photo 1. Photo taken from the battery location, facing West. Operator needs to remove unused equipment per Rule 603.f.



Photo 2. Photo taken from the battery location, facing South. See comments under Photo 1.