

Schneider Energy Services INC, Nugget Unit-Wagers 2  
121-06421  
Inspection #688300845  
12/20/2017  
SI Well



Schneider  
Energy Services, Inc. SCHNEIDER ENERGY SERVICES, INC.  
NUGGET UNIT - WAGERS #2  
SW/SE SEC.20-T1S-R56W  
IN CASE OF EMERGENCY CALL: 970-370-2944

12.20.2017





Weeds.

12.20.2017





In Case of  
Emergency Call  
970-70-2944

Schneider  
Energy Services, Inc.

SCHNEIDER  
ENERGY SERVICES, INC.

NUGGET UNIT BATTERY  
RD B & RD 26, 1/2 E

12.20.2017





12.20.2017





12.20.2017



# CRUDE OIL 500 BBL

**HEALTH HAZARD**  
4 Deadly  
3 Extreme Danger  
2 Hazardous  
1 Slightly Hazardous  
0 Normal Material

**FIRE HAZARD**  
Flash Points  
4 Below 73° F  
3 Below 100° F  
2 Below 200° F  
1 Above 200° F  
0 Will not burn



**SPECIFIC HAZARD**  
Oxidizer OX  
Acid ACID  
Alkal ALK  
Corrosive COR  
Use NO Water W  
Radioactive R

**REACTIVITY**  
4 May detonate  
3 Shock and heat may detonate  
2 Violent chemical change  
1 Unstable if heated  
0 Stable

**In Case of  
Emergency Call:  
970-370-2944**  
In Case of Fire or Medical Emergency Call: 911

12.20.2017



# CRUDE OIL

HEALTH HAZARD  
4 Deadly  
3 Extreme Danger  
2 Hazardous  
1 Slightly Hazardous  
0 Normal Material

FIRE HAZARD  
Flash Points  
4 Below 72°F  
3 Below 100°F  
2 Below 200°F  
1 Above 200°F  
0 Will not burn



SPECIFIC HAZARD  
Oxidizer OX  
Acid ACID  
Alkal ALK  
Corrosive COR  
Use NO Water W  
Radioactive R

REACTIVITY  
4 May detonate  
3 Shock and heat may detonate  
2 Violent chemical change  
1 Unstable if heated  
0 Stable

**In Case of  
Emergency Call:  
970-370-2944**

**In Case of Fire or Medical Emergency Call: 911**

12.20.2017




Stained soil at 300  
BBL crude oil tank.



12.20.2017



A large, cylindrical metal tank, likely a crude oil storage tank, is the central focus. The tank's surface is heavily weathered, with a mix of grey, brown, and greenish-grey patches. A prominent horizontal band of peeling paint reveals a dark green undercoat. The ground around the tank is dry, dusty, and stained with dark, irregular patches of soil. In the background, a flat, arid landscape stretches to the horizon under a clear sky.

Stained soil at 300 BBL  
crude oil tank.

12.20.2017





Stained soil at 300 BBL  
crude oil tank/valve on  
west side.

12.20.2017





12.20.2017



