

Inspection Photos
Location Name: Leffler 1-27
API #: 05-123-10587
Location ID: 319054



Wellhead looking south. Wellhead sign reading Leffler 27-1, well is the Leffler 1-27



Unused equipment northeast of separator



Inspection Photos
Location Name: Leffler 1-27
API #: 05-123-10587
Location ID: 319054




Battery looking south



2" steel unused/unmarked riser south of gas meter run

Inspection Photos
Location Name: Leffler 1-27
API #: 05-123-10587
Location ID: 319054



Battery sign reading Leffler 1 not Leffler 1-27