

Inspection Photos
Location Name: Stites Pad
Location ID: 334519



Photo 1. Risers have been removed.



Photo 2. Trash has been removed.