



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: NORTHERLY



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: EASTERLY

REV: 1 10-19-17 J.J. (UPDATE PHOTOS)

BILL BARRETT CORPORATION

CRYSTAL STATE #13-4
2001' FSL 671' FWL
NW 1/4 SW 1/4, SECTION 4, T3N, R62W, 6th P.M.
WELD COUNTY, COLORADO



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017

DRAWN BY: J.M.C.

DATE DRAWN: 11-20-15

TAKEN BY: J.C.

LOCATION PHOTOS

PHOTO 1



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: SOUTHERLY



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: WESTERLY

REV: 1 10-19-17 J.J. (UPDATE PHOTOS)

BILL BARRETT CORPORATION

CRYSTAL STATE #13-4
2001' FSL 671' FWL
NW 1/4 SW 1/4, SECTION 4, T3N, R62W, 6th P.M.
WELD COUNTY, COLORADO



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017

DRAWN BY: J.M.C.	DATE DRAWN: 11-20-15
TAKEN BY: J.C.	
LOCATION PHOTOS	PHOTO 2