

Inspection Photos

Location Name: Top Operating – Serafini/Powell Battery

Location ID: 318928

Inspection Date: 05/09/2017



Photo #1 – Tank Battery Sign



Photo #2 – Serafini 1 Wellhead



Inspection Photos

Location Name: Top Operating – Serafini/Powell Battery

Location ID: 318928

Inspection Date: 05/09/2017



Photo #3 – Tank battery

Photo #4 – Fence post, one of several on the ground

Inspection Photos

Location Name: Top Operating – Serafini/Powell Battery

Location ID: 318928

Inspection Date: 05/09/2017



Photo #5 - Trash



Photo #6 – Another example of trash strewn on the location

