



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 3. View of kochia (*Kochia scoparia*) debris from the previous growing season growing along the western portion of the project area.



Photo 4. View of area that is approximately 25 feet wide and 50 feet long in the western portion of the project area where vegetation is largely dead or weeds. This area needs revegetation during spring seeding window in 2018. Soil sampling/remediation may be needed.

