

Location Name: Gremlin 23-35 Spill #: 453581

Inspection Date: 12/27/2017



12.27.2017 12:14



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Gremlin 23-35 Spill #: 453581

Inspection Date: 12/27/2017



Spill location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Gremlin 23-35 Spill #: 453581

Inspection Date: 12/27/2017



Spill location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Gremlin 23-35 Spill #: 453581

Inspection Date: 12/27/2017



Spill location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Gremlin 23-35 Spill #: 453581

Inspection Date: 12/27/2017



Wellhead



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Gremlin 23-35 Spill #: 453581

Inspection Date: 12/27/2017



Wellhead equipped with two transducers.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: Gremlin 23-35 Spill #: 453581

Inspection Date: 12/27/2017



Secondary containment berm on west side of well pad.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources