




## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Dec 21, 2017 10:31:33 AM MST
Server Receive Date:	Dec 21, 2017 10:33:09 AM MST
Reference Number:	20171221-1870945410
Location:	3601 N 1st St, Bloomfield, NM 87413, United States
	Dec 21, 2017 10:31:30 AM MST [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Dec 15, 2017
Well Name	TYNER LUNT SWD
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Other Install Rock Run Down Replaced/Repaired Tank Signs

## Picture North to South



## Picture South to North



## Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

