



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Dec 30, 2017 8:09:43 PM MST
Server Receive Date:	Dec 30, 2017 8:09:56 PM MST
Reference Number:	20171231-1871245256
Location:	6 Road 3335, Aztec, NM 87410, United States
	Dec 30, 2017 8:07:30 PM MST [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Dec 28, 2017
Well Name	WOMMER GAS UNIT A 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down

## Picture North to South



## Picture South to North



## Picture East to West



Picture West to East



Additional photos

