

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2017

Submitted Date:

12/30/2017

Document Number:

671000817**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
418695 _____ DURAN, JOHN _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Findings:**5 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections
Mehennett, Tom	(719) 275-3040/ (505) 330-1328	tbm3040@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418701	WELL	WO	10/12/2012	LO	043-06196	CHANDLER CREEK 24-32	TA

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment: Wellhead			
Corrective Action:			Date:
Type: Deadman # & Marked	# 0		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 418701 Type: WELL API Number: 043-06196 Status: WO Insp. Status: TA

Cement

Cement Contractor

Contractor Name: Javernick Oil

Contractor Phone: 719-275-3040

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): 8 sxs

Good Return During Job: _____

Cement Type: Quikrete 5000

Comment: On site at 2:15 pm. There are 8sxs in hole by 2:45 pm (on top of wooder plug and 2 sxs). The cement : Quikrete 5000 Commercial Grade. There are 10 sxs total in hole. Will tag this plug and finish plugging after Jan. 1, 2018. Off site at 3:05 pm.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On site at 2:15 pm. An additional 8 sxs was put downhole. Will tag this plug and finish plugging after Jan. 1, 2018. Off site at 3:05 pm.	duranj	12/21/2017