

SGU 8501A-36 B36  
Api# 05-045-18996  
Inspection # 689700823



Location sign photo taken from north.

SGU 8501A-36 B36  
Api# 05-045-18996  
Inspection # 689700823



Location photo taken from north.

SGU 8501A-36 B36  
Api# 05-045-18996  
Inspection # 689700823



**4" riser unmarked, no plug, valve, and no lock out tag out.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



SGU 8501A-36 B36  
Api# 05-045-18996  
Inspection # 689700823



**4" riser unmarked, no plug, valve, and no lock out tag out.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources