

Inspection Photos

Location Name: Ridgeview #32-16-1

API: 081-07747



Photo taken 12/28/2017, Flare Pit. Snow covered. Unable to determine if oil is still present.



Inspection Photos
Location Name: Ridgeview #32-16-1

API: 081-07747



Photo taken 12/28/2017. Oil on ground around treater, it appears to be a greater amount of fluid than observed on 11/15/2017

Photo taken 12/28/2017. Oil on ground around treater, it appears to be a greater amount of fluid than observed on 11/15/2017



Inspection Photos

Location Name: Ridgeview #32-16-1

API: 081-07747




Photo taken 12/28/2017. Oil on ground around treater, it appears to be a greater amount of fluid than observed on 11/15/2017

Photo taken 12/28/2017. Oil on ground around treater, it appears to be a greater amount of fluid than observed on 11/15/2017

