



**Photo 1. View of southern portion of the project area from the southeastern corner facing westward.**



**Photo 2. View of the northern portion of the project area from the well pad entrance facing westward.**



**Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation appears grazed and comprised of grasses that are not in identifiable form.**

