

Inspection Photos

Location Name: Ziggy USX AB 19-99HZ

API #: 05-123-31474

Location ID: 416737



Wellhead looking east. Stained soil around wellhead has been cleaned up



Northeast edge of location looking south. Unused fencing has been removed