




## Form Information


Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 3, 2018 2:15:42 PM MST
Server Receive Date:	Jan 3, 2018 2:15:47 PM MST
Reference Number:	20180103-1871348990
Location:	100-170 S Skylane Dr, Durango, CO 81303, USA Jan 3, 2018 2:15:39 PM MST [ <a href="#">View Map</a> ]

## Information


Name	reclamationtablet
Date	Jan 2, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NW Team
Well Name	MCMAHAN GAS UNIT 2
API Number	50670834400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Completed work description

Cut and removed kochia weed debris.